

Bluesbreaker


Components

C1	10nF	R1	1M	GAIN	100K Linear
C2	47pF	R2	4K7	VOLUME	100K Log
C3	10nF	R3	3K3	TONE	25K Linear
C4	10nF	R4	1M	TREBLE	solder jumper as shown below
C6	100nF	R5	Jumper		
C7	10nF	R6	4K7	D1-4	1N4148
C8	10nF	R7	4K7	D5-6	none
C9	100nF	R8	6K8	D7	1N4001
C10	100uF Electrolytic	R9	220K		
C11	100uF Electrolytic	R10	6K8	IC1	TL072
C12	none	R11	1K		
		R12	1M	DIODES SWITCH	solder jumper as shown below
		R13	47K		
		R14	47K		

Note: there is no C5

Jumpers

Where a component is listed as jumper, solder a piece of wire between the pads to make a connection. Where the treble trimmer is not used, you should put a jumper between pins 2 and 3 like the diagram below. If you're building the Bluesbreaker, put a jumper between the bottom two pads of the DIP switch



Treble



Diodes

Bluesbreaker

Board Connections

The PCB connections are labelled as the following:

I - Input, O - Output, V - 9V DC in, G - Ground

Potentiometers are connected from pin 1 to the square pad on the PCB. This board was designed so you can use right-angle board mount potentiometers on it if desired, otherwise you will need to solder wires from the pads to the correct pin/lug. Jack sleeves and DC centre pin should be connected to ground. V should be connected to the positive pin of the DC connector.

